
Diagnoza/Reparatie/Inlocuire Turbina Mercedes Citan 1.5 Diesel

I.D.: 58830300

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 13.07.21 | Coduri CPV | 50112100-4 |
|-----------------|----------|------------|------------|

| | |
|-------------------|-----------------------------|
| Pretul estimativ: | 1.907,29 RON - 1.907,29 RON |
|-------------------|-----------------------------|

| | |
|------------|--|
| Descriere: | DIAGNOZA SI REPARATIE MERCEDES CITAN(INLOCUIRE TURBINA) CU NR DE INMATRICULARE PH 23 DPO |
|------------|--|
