

PACHET MATERIALE INTRETINERE SI REPARATII

I.D.: 83879683

Data publicarii	22.06.23	Coduri CPV	44192000-2
-----------------	----------	------------	------------

Pretul estimativ: 2.483,64 RON - 2.483,64 RON

Descriere: Cablu CYYF 5x4 4ml x 13,03 ron, broasca simpla 25x92 2 buc x 38,66 ron, email Ideea verde 0,75l 1 buc x 22,69 ron, diblu tox 12x76 50 buc x 0,84 ron, teu alama 3/4 5 buc x 13,02 ron, robinet bila 3/4 IE 4 buc x 16,81 ron, racor PPR 25x3/4FI 2 buc x 4,62 ron, racord PPR 25x3/4 FE 2 buc x 9,24 ron, surub lemn hex 25 buc x 0,84 ron, surub lemn 10x120 25 buc x 1,09 ron, surub lemn 6x120 25 buc x 0,50 ron, teava PVC U 11x1m 4 buc x 15,13 ron, teava PP 11x0,5m 3 buc x 10,92 ron, teava PP 110x0,25ml 3 buc x 7,56 ron, cot PP 110x87,5 ron, piesa curatire PVC 110 2 buc x 13,44 Ron, ramificatie PP 110x110x45 3 buc x 10,92 ron, ramificatie PP 110x110x87 2 buc x 10,92 ron, teava PP 50x1,00 ml 4 buc x 6,72 ron, tub PVC VLP 50/0,25 12 buc x 2,94 ron, ramificatie PP 50x50x45 4 buc x 3,36 ron, cot PP 50x45 10 buc x 1,68 ron, sifon pardoseala 105x105 3 buc x 39,50n ron, reductie PP 110x50 1 buc x 3,36 ron, piesa curatire 50 2 buc x 7,56 ron, robinet flotor WC 5 buc x 23,53 ron, silicon sanitar alb Bison 280ml 5 buc x 20,17 ron, cot PP 5x45 10 buc x 1,68 ron, stecher IP44 5x32A 2 buc x 26,05 ron, priza PT 5x32A 2 buc x 46,22 ron, surub guler 8x30 10 buc x 1,51 ron, surub guler 10x60 10 buc x 2,52 ron, piulita flansa AB M8 10 buc x 1,51 ron, piulita flansa AB M10 10 buc x 0,84 ron, teava flexibila Alca A75 10 buc x 5,88 ron, teava scurgere A75+A31 cu ventil 10 buc x 14,29 ron, teava PP 75x1ml 2 buc x 10,92 ron, email 3in1 argintiu 0,75l 9 buc x 36,97 ron, perie sarma maner lung 3 buc x 9,24 ron,
