
Servicii de reparare regulator de turatie Woodward tip PGA, UG-8, UG-40

I.D.: 45406371

Data publicarii	06.04.20	Coduri CPV	50531000-6
-----------------	----------	------------	------------

Pretul	13.800,00 RON - 13.800,00 RON
estimativ:	117.906,00 RON - 117.906,00 RON
	11.400,00 RON - 11.400,00 RON

Descriere: 3. Serviciu reparare regulator de turatie Woodward tip UG-40, Serviciu reparare regulator de turatie Woodward tip UG-40, Acordul cadru: min 1 serv, max 2 serv, Contract subsecvent: min 1 serv, max 2 serv.. 1. Serviciu reparare regulator de turatie Woodward tip PGA, Serviciu reparat regulator de turatie Woodward tip PGA; Acord-cadru: min 1 serv, max 12 serv; Contract subsecvent: min 1 serv, max 4 serv. 2. Serviciu reparare regulator de turatie Woodward tip UG-8, Serviciu reparare regulator de turatie Woodward tip UG-8, Acord cadru: min 1 serv, max 2 serv, Contract subsecvent: min 1 serv, max 2 serv.
