

REVIZIE+REPARATIE DOKKER, SKODA OCTAVIA, VW KOMBI

I.D.: 48335559

Data publicarii 20.07.20 Coduri CPV 50110000-9

Pretul estimativ: 4.447,06 RON - 4.447,06 RON

Descriere: MATERIALE: Placute frana fata 1x92.44=92.44 ; Filtru ulei 1x21.85=21.85 ; Filtru motorina 1x73.95=73.95 ; Filtru aer 1x38.66=38.66 ; Filtru polen 1x31.93=31.93 ; Ulei Castrol edge 5w30 5l 1x210.08=210.08 MANOPERA: DR placute frana fata 1.00x42.02=42.02 ; Revizie (ulei+filtre) 2.00x42.02=84.04 ; Test franare 0.6x42.02=25.21 MATERIALE: Volanta+ kit ambreaj LUK 1X1533.61=1533.61 ; Bec H4 1X29.41=29.41 ; Bec numar 1x8.40=8.40 MANOPERA: DR cv de pe auto 8.00x42.02=336.16 ; DR volanta + kit ambreaj 1.00x42.02=42.02 MATERIALE: Ulei Castrol edge 5w30 5l1x210.08=210.08 ; Ulei Castrol edge 5w30 1l 2x46.22=92.44 ; Filtru ulei 1x36.97=36.97 ; Filtru aer 1x37.81=37.81 ; Filtru combustibil 1x193.28=193.28 ; Filtru polen 1x52.10=52.10 ; Pompa strop gel 1x54.62=54.62 ; Bucsi bara stabilizatoare 2x29.41=58.82 ; Bieleta antiruliu 2x75.63=151.26 ; Bucsi brat inferior cele din spate 2x53.78=107.56 ; Placute frana fata 1x122.69=122.69 ; Bec 2x8.40=16.80 ; Pivot stg fata 1x107.56=107.56 MANOPERA: Revizie (ulei+filtre) 2.00x50.42=100.84 ; DR pompa strop gel 1.00x50.42=50.42 ; DR bucsi bara stabilizatoare 2x0.5x50.42=50.42 ; DR bieleta antiruliu 2x0.8x50.42=80.67 ; DR brat inferior si inlocuit bucsi 2x2.00x50.42=201.68 ; DR placute frana fata 1.00x50.42=50.42 ; DR pivot stg. fata 1.5x50.42=75.63 ; Test franare 0.5x50.42=25.21