

---

## Service stingatoare sediu

I.D.: 93121852

---

Data publicarii	06.02.24	Coduri CPV	50413200-5
-----------------	----------	------------	------------

---

Pretul estimativ:	468,00 RON - 468,00 RON
-------------------	-------------------------

---

Descriere: Servicii verificare stingatoare sediu conform descriere: Service stingator P6 pisele, subansamblele defecte si agentul de stingere se factureaza separat - 23 buc si SERVICE STINGATOR G2 PIESELE, SUBANSAMBLELE DEFECTE SI AGENTUL DE STINGERE SE FACTUREAZA SEPARAT- 3 buc

---