

---

## Reparatie masina de spalat Candy 10 kg

I.D.: 41958560

---

Data publicarii	25.02.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 290,00 RON - 290,00 RON

---

Descriere: - Constat defect: 40.00 Ron - Materiale folosite: - Pompa 40 W: 35.00 Ron - Filtru: 25.00 Ron - Inlocuit subansamble (pompa 40 W): 130.00 Ron - Curatare traseu evacuare: 35.00 Ron - Proba functionare: 25.00 Ron la Centrul pentru Persoane Vârstnice Fierbinti

---