
Reparatie Cuptor HP P 2035 inlocuire FUSER UNIT

I.D.: 107346529

Data publicarii	19.12.24	Coduri CPV	50323200-7
-----------------	----------	------------	------------

Pretul estimativ: 319,32 RON - 319,32 RON

Descriere: Reparatie Cuptor HP P 2035 inlocuire FUSER UNIT Specificatii FUSER UNIT 2035 Functioneaza in urmatoarele imprimante: HP LaserJet P2035, LaserJet P2035n, LaserJet P2055d, LaserJet P2055dn, LaserJet P2055x; Canon image CLASS D1120, D1150, D1170, D1180, D1320, D1350, D1370, D1520, D1550, LBP251dw, LBP253dw, LBP6670dn, MF414dw, MF416dw, MF419dw, MF5850dn, MF5880dn, MF5950dw, MF5960dn, MF6160dw, MF6180dw, Canon image RUNNER LBP3470, LBP3480, Canon LASER CLASS 650i Acest produs este pentru HP Compatibilitate HP LaserJet P2035, LaserJet P2035n, LaserJet P2055d, LaserJet P2055dn, LaserJet P2055x; Canon imageCLASS D1120, D1150, D1170, D1180, D1320, D1350, D1370, D1520, D1550, LBP251dw, LBP253dw, LBP6670dn, MF414dw, MF416dw, MF419dw, MF5850dn, MF5880dn, MF5950dw, MF5960dn, MF6160dw, MF6180dw, Canon imageRUNNER LBP3470, LBP3480, Canon LASER CLASS 650i OEM no RM1-6406-000
