

---

## Reparatie picon EPIROC EC40T #BES-105539

I.D.: 62600878

---

|                 |          |            |            |
|-----------------|----------|------------|------------|
| Data publicarii | 01.11.21 | Coduri CPV | 50000000-5 |
|-----------------|----------|------------|------------|

---

Pretul estimativ: 9.952,34 RON - 9.952,34 RON

---

Descriere: 1 SET GARNITURI 1,00 BUC 1.868,50 1.868,50 355,02 2 BUCSA SPIT PICON 1,00 BUC 2.728,75 2.728,75 518,46 3 BOLT BUCSA 1,00 BUC 444,00 444,00 84,36 4 SIGURANTA BOLT 1,00 BUC 10,09 10,09 1,92 5 GRESOR 1,00 BUC 18,50 18,50 3,52 6 SPIT PICON (CONIC) 1,00 BUC 1.295,00 1.295,00 246,05 7 Manopera constatare 2,00 ORE 175,00 350,00 66,50 8 Manopera reparatie 16,00 ORE 175,00 2.800,00 532,00 9 Incarcare cu azot 1,00 ORE 175,00 175,00 33,25 10 VENITURI CONSUMABILE SERVICE 1,00 - 262,50 262,50 49,88

---