
Pachet reparatie Fiat Ducato

I.D.: 67246902

Data publicarii	14.03.22	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.314,81 RON - 1.314,81 RON

Descriere: Unitate de control bujii incandescente 1 buc 142,86 ron Senzor, turatie roata 1 buc 126,00 Bujie incandescenta 4 buc 67,16 ron Verificat Bujii 75,63 ron Inlocuit releu bujii 71,43 ron Inlocuit senzor ABS 117,65 ron Testat motor 50,42 ron Inlocuit bujii incandescente 462,18 ron
