



reparat POMPA WILO 4.8KW/3000T

I.D.: 43579838

Data
publicarii

06.03.20

Coduri CPV

50511000-0

Pretul
estimativ:

5.020,00 RON - 5.020,00 RON

Descriere: Oferta refuzata: demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansari
mecanice, reparat cablu alimentare +ulei siliconic
