
Serviciu de reparatie instalatie de incalzire

I.D.: 32035681

Data publicarii	15.11.18	Coduri CPV	50721000-5
-----------------	----------	------------	------------

Termenul limita pentru depunere: 19.11.18

Descriere: Serviciu de reparatie instalatie de incalzire, care include inlocuire teava PPR 50 mm (36 ml); mufa PPR 50 mm (6 buc); cot PPR 50 (10buc); Teu PPR 50x20x50 (14 buc); teava PPR 20mm (8ml); cot PPR 20mm (20 buc); adaptor PPR 20x 1/2" FE (18 buc); cot adaptor PPR 20x1/2" (6 buc); mufa conector 16x1/2" (6 buc); colier cu diblu 50mm (30 buc).
