
REPARATII IMPRIMANTE

I.D.: 88628072

Data
publicarii 26.10.23

Coduri CPV

50323200-7

Pretul
estimativ: 896,00 RON - 896,00 RON

Descriere: REPARATIE IMPRIMANTA CANON , REPARATIE FUSER CUPTOR, RECALIBRARE REPARATIE /
remediere unitate fuser BROTHER 5750 , sensor ghidaj, rola presoare
