

---

## **Pachet reparatie aparatura de laborator**

I.D.: 101785595

---

Data publicarii	20.08.24	Coduri CPV	50410000-2
-----------------	----------	------------	------------

---

Pretul estimativ: 5.490,00 RON - 5.490,00 RON

---

Descriere: 1. Reparare si calibrare incubator Binder KB53 serie 03-43517, piese de schimb incluse (compresor, freon, manopera) 1 buc. \* 2.890,00 RON 2. Cheltuieli interventie (transport echipamente) 1 buc. \* 800,00 RON 3. Revizie tehnica si curatare chimica bidistilator GFL (set furtunuri inclus) 1 buc. \*1.800,00 RON

---