

Servicii de reparare masina de spalat Indesit

I.D.: 63573545

Data publicarii	25.11.21	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 410,00 RON - 410,00 RON

Descriere: Reparatie masina de spalat rufe Indesit , inlocuit rulmenti si semeringuri , debitat cuva de polipropilena si etansat la aDGASPC SECT.1 / C.A.R. PAD Milcov
