

---

## Piese schimb instalatie de dioxid de clor

I.D.: 105308289

---

Data publicarii	07.11.24	Coduri CPV	34913000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 11.088,80 RON - 11.088,80 RON

---

Descriere: Reparatie pompa dozare clorit prin inlocuire biela: Reparatie pompa dozare clorit prin inlocuire biela (PM-1036735) Manopera inclusa; Revizie instalatie de dioxid de clor: Include: 1 x Kit service CDVc 14, 2.000 g/h (PM-1048801) Manopera si deplasare incluse.

---