
SERVICII REPARATIE LA SCHIMBATOR DE CALDURA PENTRU AGREGAT TIP CHILLER;Servicii de reparatie agregat

I.D.: 39226302

Data publicarii	18.10.19	Coduri CPV	50531000-6 50532000-3
-----------------	----------	------------	-----------------------

Pretul estimativ:	15.130,00 RON - 15.130,00 RON
-------------------	-------------------------------

Descriere:	SERVICII REPARATIE LA SCHIMBATOR DE CALDURA PENTRU AGREGAT TIP CHILLER;Servicii de reparatie agregat
------------	--
