



reparatii auto-SV20SMF,SV52SMF

I.D.: 73676644

Data publicarii	30.09.22	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 2.006,73 RON - 2.006,73 RON

Descriere: Schimb placute frana spate, inlocuit culisoare+ITP; Diagnoza, inlocuit racitor gaze si supapa EGR, inlocuit clapeta admisie Achizitia din SEAP tine loc de comanda
