
REPARATIE VOLKSWAGEN TRANSPORTER

I.D.: 46112368

Data publicarii	05.05.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.565,39 RON - 1.565,39 RON

Descriere: Cost manopera inlocuit suport motor, extragere surub bloc motor, inlocuit si echilibrat anvelope. Cost piese schimb: suport motor, suport superior motor, surub - 7 buc.
