
Reparatie imprimanta HP 5100

I.D.: 42305529

Data publicarii	20.03.19	Coduri CPV	30232110-8
-----------------	----------	------------	------------

Pretul estimativ: 1.191,53 RON - 1.191,53 RON

Descriere: Fuser Maintenance Kit 220V - Q1860-69033 Imprimanta HP LASERJET 5100 Q1860-69033
Fuser assembly + kit role +manopera inlocuire piese
