
Repartie pompe Epurare

I.D.: 68926322

Data publicarii	05.05.22	Coduri CPV	50532100-4
-----------------	----------	------------	------------

Pretul estimativ: 6.750,00 RON - 6.750,00 RON

Descriere: Nr.neces.112/11.04.2022-Reparatia consta in inlocuirea etansarilor mecanice , schimbare presutupa, ulei , rulementi si rotor hidraulic.,Nr.neces.128/02.05.2022 Reparatia consta in rebobinare, inlocuire etansari , inlocuire rulmenti .
