
Reparatii dulap HPM M660A

I.D.: 50410301

Data publicarii	05.10.20	Coduri CPV	42512300-1
-----------------	----------	------------	------------

Pretul estimativ: 2.505,00 RON - 2.505,00 RON

Descriere: Reparatie sistem detectie apa (inclusiv soclu releu + releu 24V/5A) Izolatie traseu frigorific (izolatie armaflex, panza anticondens, banda de matisare) Reparatie instalatie umidificacare Freon R407C kg 10 Reglare aparat
