
EAA001715AMB61rev reparatii T5

I.D.: 52054670

Data publicarii	27.11.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 5.134,47 RON - 5.134,47 RON

Descriere: Piese materiale Bieleta antiruliu 1buc x 42,05 Garnitura 1buc x 7,56 Racitor supapa EGR 1buc x 890,76 Garnitura EGR 1buc x 12,61 Set ambreiaj cu volanta 1buc x 2853,78 Ulei C/V (1L) 3buc x 46,22 Lichid frana (0,5L) 1buc x 21,01 Senzor presiune ulei 1buc x 21,85 Spray degripant 1buc x 18,49 Solutie de curatat 4buc x 10,08 Antigela (1L) 1buc x 13,45 TOTAL PIESE/MATERIALE 4100,86 Manopera aferenta 1033,61 TOTAL DEVIZ 5134,47 fara TVA
