
servicii reparatie imprimanta HP1320,servicii reincarcare cartus imprim Canon LBP 3300

I.D.: 56269175

Data publicarii	20.04.21	Coduri CPV	50312000-5 50323000-5
-----------------	----------	------------	-----------------------

Pretul estimativ:	240,00 RON - 240,00 RON
-------------------	-------------------------

Descriere:	servicii reparatie imprimanta HP1320(inlocuire pickup roller),servicii reincarcare cartus imprim Canon LBP 3300
------------	---
