



Achizitie servicii reparatie auto/revizie CL26SUD ADRSM

I.D.: 63459927

Data publicarii	23.11.21	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ:	1.707,38 RON - 1.707,38 RON
-------------------	-----------------------------

Descriere: Skoda Rapid CL26SUD - Inspectie service cu inlocuire ulei motor, filtru ulei, aer, polen, curea alternator si intinzator = piese + manopera.
