
Reparatie Mercedes Benz Sprinter

I.D.: 77870980

Data publicarii	25.01.23	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 4.410,92 RON - 4.410,92 RON

Descriere: Reparatie Mercedes Benz Sprinter INLOCUIRE CUREA DE TRANSMISIE LA AV,INLOCUIRE ROLA DE GHIDARE,BIELETA DE DIRECTIE STANGA+DREAPTA,UNGHII CONVERGENTA ROTI FATA,INLOCUIRE LA CONSTATARE ELEMENT AM,CUREA W906,ROLA GHIDAJ,ROLA CANELATA,BIELETA CAP SFERIC,AMORTIZOR FATA,SURUB REGLAJ
