



Serviciu de reparatie- Volkswagen Transporter

I.D.: 52057174

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 27.11.20 | Coduri CPV | 50110000-9 |
|-----------------|----------|------------|------------|

Pretul estimativ: 5.458,36 RON - 5.458,36 RON

Descriere: Serviciu de reparatie Volkswagen Transporter -inlocuit kit distributie+pompa apa -inlocuit kit transmisie -inlocuit ulei+filtre -D/R coloana evacuare +inlocuit toba catalizator -inlocuit bujii incandescente -inlocuit placute frana fata+spate TOTAL piese+materiale+manopera=5458.36
