
reparatie Dacia Duster CL 39 HHS

I.D.: 101825617

Data publicarii	21.08.24	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 5.281,88 RON - 5.281,88 RON

Descriere: SISTEM RACIRE-INLOCUIT COMPRESOR,RADIATOR AC SI VENTILATOR,SISTEM FRANARE-SABOTI FRANA CU CILINDRII FRANA,PLACUTE FRANA SI CABLURI FRANA DE MANA,HUSE SCAUN+MANOPERA
