
Reparat 2 pompe Flygt

I.D.: 51956475

Data
publicarii 25.11.20

Coduri CPV

50511000-0

Pretul
estimativ: 3.220,00 RON - 3.220,00 RON

Descriere: reparat POMPA FLIGHT1.2KW/3000T - demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansare mecanica, ulei,diverse
