
Reparatie B 100 THF

I.D.: 93688881

Data publicarii	19.02.24	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 13.915,01 RON - 13.915,01 RON

Descriere: Servicii de remediere a defectiunilor constatate la autosanitara cu nr. B100THF, folosind urmatoarele piese de schimb si materiale consumabile: SET lant DISTRIB AX CAME (lant, pinioane, intinzator, patina) Set distributie (curea + rola intinzator + rola ghidare/conducere) Pompa apa+antigel Set tchet cu culbutor 504074464 Simering ax came admisie Set inj cu surub oring si saiba inj Ax came admisie+evacuare Pinion si capac ax came Ulei motor 5w30/7L Longlife Filtru ulei Filtre combustibil/polen/aer
