
Reparatie analizor URISED 2

I.D.: 51138429

Data publicarii	29.10.20	Coduri CPV	50421000-2 50400000-9
-----------------	----------	------------	-----------------------

Pretul estimativ: 2.968,00 RON - 2.968,00 RON

Descriere: Continut: Valoare service: 750 RON + TVA S-URS43056-microscop control card: 1 buc x 1015 RON + TVA S-URP42033- led driver PCB: 1 buc x 188 RON + TVA S-URS43046-rack control card : 1 buc x 1015 RON + TVA
