

Reparatii PERFUSOR SPACE seria 566718, INFUSOMAT COMPACT PLUS seria 4377, PERFUSOR COMPACT PLUS

I.D.: 77890058

Data publicarii 27.01.23 Coduri CPV 50000000-5 50420000-5

Pretul estimativ: 6.332,29 RON - 6.332,29 RON

Descriere: Reparatii PERFUSOR SPACE seria 566718, INFUSOMAT COMPACT PLUS seria 4377, PERFUSOR COMPACT PLUS seriile 14800 si 14810 = 6332.29 LEI FTVA PERFUSOR SPACE seria 566718
COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE
SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00
34521041 DRIVE PSP COMPLETE GREEN CLAWS (sistem complet de actionare seringa) 1
1836.17 1836.17 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10 1.04
10.40 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 · INFUSOMAT
COMPACT PLUS seria 4377 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA
VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material
service) 1 50.00 50.00 34522000 POWER SUPPLY CP (alimentator CP) 1 264.96 264.96
34522116 DISPLAY BOARD WITH DISPLAY CP (Display CP) 1 354.70 354.70 34522202 SENSOR
PCB ICPS (placa sensor ICPS) 1 232.88 232.88 SERVICII REPARATII MANOPERA REPARATII
+CALIBRARE+TSC 1 0 0 · PERFUSOR COMPACT PLUS seria 14800 COD DESCRIERE CANTITATE
(buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM
FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522105 DRIVE COMPLETE PCP
(system de actionare seringa PCP) 1 1653.54 1653.54 SERVICII REPARATII MANOPERA
REPARATII +CALIBRARE+TSC 1 0 0 · PERFUSOR COMPACT PLUS seria 14810 COD DESCRIERE
CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001
LUMP SU