
REPARATIE AUTO PH.23.CSB

I.D.: 105290491

Data publicarii	07.11.24	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 6.395,71 RON - 6.395,71 RON

Descriere: FURTUN ADMISIE AER STANGA 1X218.49 , SPREI CURATARE 5X21.01 , ULEI MOTOR FORD 2X184.87 , ULEI MOTOR FORD 1X42.02 , BUSON GOLIRE BAIE ULEI 1X21.01 , DILUANT 2X10.08 , TURBOCOMPRESOR 1X3109.24 , FILTRU ULEI 1X25.21 , FILTRU AER 1X33.61 , FURTUN ADMISIE 1X243.70 , SUPAPA EGR 1X563.03 , FURTUN ADMISIE AER DREAPTA SUPERIOR 1X189.08 , SURUB TURBINA 3X8.40 , PIULITA GALERIE EVACUARE 2X4.20 , GARNITURA CATALIZATOR 1X16.81 , RADIATOR INTERCOOLER 1X882.35 , SURUB GALERIE EVACUARE 3X4.20 , MANOPERA SERVICE 5.10X100.
