

---

## Reparatie imprimanta HP 5100 319

I.D.: 42302142

---

Data publicarii	19.03.19	Coduri CPV	30232110-8
-----------------	----------	------------	------------

---

Pretul estimativ: 1.191,53 RON - 1.191,53 RON

---

Descriere: Fuser Maintenance Kit 220V - Q1860-69033 Imprimanta HP LASERJET 5100 Q1860-69033  
Fuser assembly + kit role +manopera inlocuire piese

---