
reparatie Dacia Duster CL 04 PWM CL

I.D.: 73147027

Data publicarii	12.09.22	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	912,27 RON - 912,27 RON
-------------------	-------------------------

Descriere:	INLOCUIT TERMOSTAT SI VERIFICAT INSTALATIE SISTEM RACIRE
------------	--
