

Servicii de Reparatii NT 07 BBK

I.D.: 44191651

Data publicarii	10.10.19	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 9.583,23 RON - 9.583,23 RON

Descriere: Cap bara stg- dr x 2 buc = 195.00, set placute frana fata x 1 buc = 218.49, bieleta antirului spate x 2 buc = 193.28, set distributie x 1 set = 407.56, pompa apa x 1 buc = 447.90, curea transmisie x 1 buc = 139.50, intinzator curea accesorii x 1 buc = 200.84, rola transmisie x 1 buc = 110.08, ulei Ravenol 5w 30 x 7 l = 382.35, filtru ulei x 1 buc = 50.42, filtru aer x 1 buc = 86.55, filtru combustibil x 1 buc = 75.63, anvelope 225/75/R16 C x 4 buc = 1.277,31, spray degripant x 1 buc = 21.01, spray ceramic x 1 buc = 58.82, coliere metalice x 6 buc = 20.17, antigel x 4l = 84.03, tripodaint dr x 1 buc = 327.73, burduf planetara x 1 buc = 75.63, rulment roata fata x 2 buc = 571.43, aripa dr fata x 1 buc = 243.70, carenaj fata dr x 1 buc = 142.86, ulei cutie x 3 buc = 88.24, scut motor fata dr x 1 buc = 117.65, banda protectie roata dr fata x 1 buc = 159.66, bec auto x 3 buc = 12.61, plasa palier fara st-dr x 1 buc = 151.26, bucsa flansa palier x 1 buc = 58.82, suport numar x 1 buc = 8.4, mecanism culisaj jos x 1 buc = 264.71, mecanism culisaj susu x 1 buc = 297.48, mecanism culisaj mijloc x 1 buc = 277.31, senzor ABS stg spate x 1 buc = 176.47, pompa frana x 1 buc = 573.11, colier metalic x 2 buc = 8.4, lichid frana x 1 buc = 16.81, servicii vulcanizare x 1.68 norma = 84.03, convergenta directie x 3.36 norma = 168.07, manopera totala x 33.61 norma = 1680.67
