
Reparatie fax Panasonic KX-FL613FX

I.D.: 49758176

Data publicarii 16.09.20

Coduri CPV

50000000-5

Pretul estimativ: 1.086,00 RON - 1.086,00 RON

Descriere: Reparatie fax Panasonic KX-FL613FX - inlocuire rola preluare - inlocuire unitate cilindru conf. deviz
