
Reparatie auto FIAT DOBLO B 50 PYI

I.D.: 42964206

Data publicarii	06.06.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 1.032,00 RON - 1.032,00 RON

Descriere: inlocuit kit lant distrib; inlocuit pompa; manopera tinichigerie; inlocuit curea agregate; inlocuit curea servo; inlocuit antigel; sudat racord flexibil
