
Reparatie cuptor copiator ricoh mp2554

I.D.: 94341813

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 04.03.24 | Coduri CPV | 50323000-5 50300000-8 |
|-----------------|----------|------------|-----------------------|

| | |
|-------------------|-----------------------------|
| Pretul estimativ: | 1.900,00 RON - 1.900,00 RON |
|-------------------|-----------------------------|

| | |
|------------|-------------------------------------------------------------------------|
| Descriere: | Inlocuire Fusing Sleeve Unit Ricoh, curatare roke preluare si transport |
|------------|-------------------------------------------------------------------------|
