

Serviciul de reparatie Motocoasa Stihl

I.D.: 61191540

Data publicarii	20.09.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 578,47 RON - 578,47 RON

Descriere: Serviciul de reparatie consta in urmatoarele proceduri: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (carburator, cablu acc.,sorb, bujie) - testare/predare
