

---

## **REPARATIE MONITOR FV - HEMATOLOGIE**

I.D.: 35254570

---

Data publicarii	12.04.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.573,95 RON - 1.573,95 RON
-------------------	-----------------------------

---

Descriere: Constatate defect \*Reparatie modul electronic comanda HOLTER TA si PULSOXIMETRIE  
\*Inlocuire: MANSETA holter TA (UZATA), CABLU CU SENZOR PULSOXIMETRU 5 PINI(scurt circuit ) PRELUARE,DEPANARE,RETUR,PROBE FUNCTIONALE! PREZENTA TINE LOC DE COMANDA FERMA.

---