

Reparatii auto HD-08-UCM

I.D.: 64787863

Data publicarii 27.12.21 Coduri CPV 50110000-9 34300000-0

Pretul estimativ: 1.821,85 RON - 1.821,85 RON

Descriere: Remedieri mecanice diverse, geometrie directie si inlocuire piese (macara geam electric, colier esapament, antigel, set placute frana, senzor uzura olacute, bieleta directie, cap de bara stanga si cap de bara dreapta, racord evacuare, colier toba si tampon toba) la microbuzul Mercedes Benz Vito cu nr. de inmatriculare HD-08-UCM
