

---

## Service echipamente de laborator LSVSA CV

I.D.: 42846988

---

Data publicarii	23.05.19	Coduri CPV	50410000-2
-----------------	----------	------------	------------

---

Pretul estimativ: 3.673,00 RON - 3.673,00 RON

---

Descriere: Mentenanta revizie autoclav Panasonic Manopera reparatie masina de spalat Miele si autoclav Sanyo, inlocuit furtun-Water proof system Miele Conform ofertei LOP 383 din 22.05.2019

---