
Service schimb de ulei la Dacia Dokker SV 12 ZEB

I.D.: 48581399

Data publicarii	30.07.20	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ:	980,50 RON - 980,50 RON
-------------------	-------------------------

Descriere: Inlocuire ulei motor + filtre ulei, aer, polen si combustibil, inlocuire placute frana fata, citire memorie defecte cu manopera aferenta.
