
Servicii intretinere si reparatii Opel Vivaro

I.D.: 53711592

Data publicarii	25.01.21	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ:	2.295,00 RON - 2.295,00 RON
-------------------	-----------------------------

Descriere:	Inlocuire Discuri si placute frana spate, senzor ABS stanga spate
------------	---
