
REPARATIE AUTOSPECIALA IVECO

I.D.: 84147057

Data publicarii	03.07.23	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Termenul limita pentru depunere:	05.07.23	Pretul estimativ:	750,00 RON - 750,00 RON
----------------------------------	----------	-------------------	-------------------------

Descriere: Reparatie autospeciala Iveco (serie sasiu = ZCFC50A310585358, numar inmatriculare BR 23 ANP) constand in: inlocuire senzor ABS spate. Se solicita inlocuirea senzorului ABS spate intr-un service autorizat.
