

---

## Reparatie hota cu flux laminar

I.D.: 54576817

---

Data publicarii	22.02.21	Coduri CPV	50421000-2
-----------------	----------	------------	------------

---

Pretul estimativ: 8.122,00 RON - 8.122,00 RON

---

Descriere: 1 Reparatie hota cu flux laminar - inlocuit piese defecte si efectuat probe de functionare (motor; placa electronica; filtru Hepa; tub lampa UV; tub neon; geam mat; vopsea;) buc 1.00

---