

## Reparatie pompa Willo

I.D.: 60954165

---

Data publicarii	13.09.21	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 2.675,94 RON - 2.675,94 RON

---

Descriere: Reparatie pompa Willo constand din demontare ansamblu pompa, rebobinare stator, reconditionare cota etansare ax, inlocuire kit presetupa etansare mecanica inferior si superior, montare, ermetizare, probe

---