

reparatie ciller

I.D.: 75147565

Data publicarii	11.11.22	Coduri CPV	50700000-2 50421000-2
-----------------	----------	------------	-----------------------

Pretul estimativ:	7.500,00 RON - 7.500,00 RON
-------------------	-----------------------------

Descriere:	reparatie ciller cu inlocuire pompa si lichid de racire
------------	---
