

---

**KIT REPARATIE POMPA (STATORI+ROTORI) LOWARA, TIP: COD 1016L1651, PUMP UNIT:22SV05F055Q1BE66 E, Q=11-**

I.D.: 42851498

---

Data publicarii	22.05.19	Coduri CPV	50511100-1
-----------------	----------	------------	------------

---

Pretul estimativ: 1.486,96 RON - 1.486,96 RON

---

Descriere: KIT REPARATIE POMPA (STATORI+ROTORI) LOWARA, TIP: COD 1016L1651, PUMP UNIT:22SV05F055Q1BE66 E, Q=11-29 MC/H; H=70,8-28,8 M; P= 5,5 KW . Constatate preliminara: - rotorii si statorii pompei sparti; - cauze posibile: continut mare de solide in lichide, mangan

---