
serviciu de reparare si intretinere auto

I.D.: 39891201

Data publicarii	25.07.18	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.877,31 RON - 1.877,31 RON

Descriere: serviciu de reparare si intretinere vw transporter inlocuit conducta frina dr spate , etrier dr spate, REPARATIE vw transporter inlocuit rulment spate .cap bara,serviciu de reparare si intretinere dacia logan inlocuit saboti,
